
## **PowerWorx Front Access Fuse Panel Replacement**



## <u>Issue</u>:

Defective Alarm Circuit Board in the PowerWorx Fuse Panel incorrectly sets remote power alarm. Alarm contact closure has a dead short across normally open and common contacts indicating power distribution or power bus trouble. This problem only affects the ability to monitor local or remote alarms in the ADC PowerWorx distribution panel.

## **Ordering Information:**

TFC-WORX-FAM1 PowerWorx Front Access Fuse Panel Replacement

(Equiv. to ADC # TFA-FAM) (used in Remote Cabinet Sites)

150 Cooper Rd. (F-15) W. Berlin, NJ 08091

Telephone: (856) 753-8585 www.tagcords.com Fax: (856) 768-7645

**Telecom Assistance Group**