Fan Alarm Control Circuit Board Replacement — TFC-PDFA-X2



REPLACEMENT SCREWS, WASHERS AND INSULATOR INCLUDED

PLACE THE INSULATOR BETWEEN THE METAL TAB ON THE PDFA FAN TRAY AND THE DIODE ON THE ALARM BOARD.

(IF EXISTING INSULATOR IS NOT THERE)

DO NOT DOUBLE INSULATE



REMOVE AND REPLACE SHORTER SCREW AND LOCKWASHER

REMOVE AND REPLACE LONGER SCREW AND CONE WASHER





INSULATOR

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091
www.tagcords.com
Telephone: (856) 753-8585
Fax : (856) 768-7645
Telecom Assistance Group

Copyright © 2024 by Telecom Assistance Group, Inc.

OSP Cabinet Replacement Fans & Alarm Control Boards

"Litespan PDFA"

PN # TF-LS2000-01
48 Volt Replacement Fan for
Litespan 2000 Power Distribution (PDFA)

Square Fan w/ 3 Wire Plug & Guard Grill
(includes plastic rivets)
(use in PDFA Fan Tray # 500-1126-723)

NEW Alarm Control Boards
are also available,
order **# TFC-PDFA-X2**



(2 ALARM CONTROL BOARDS ARE USED IN EACH TRAY)



FAN TRAY # 500-1126-723
w/ (4) EXISTING FANS
(fan tray is not included)

Ordering Information:

TF-LS2000-01	**48 Volt Replacement Fan for LS2000 PDFA, Square Fan w/ 3 Wire Plug & Guard Grill** *(includes plastic rivets) (use in PDFA Fan Tray # 500-1126-723)*	**Call for Pricing**
TFC-PDFA-X2	**Alarm Control Board for LS2000 PDFA Fan Trays** *(equiv. to # 300-8205-900) (use in PDFA Fan Tray # 500-1126-723)*	

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group

Copyright © 2024 by Telecom Assistance Group, Inc.