OSP Cabinet Replacement Fans

"NORTEL OC12 CABINET"



FTR UPN # TF-NTOC12-01
48V Replacement Fan for
NT7H72AA found in
Nortel OC12 Cabinets

w/ 2 Wire DB9M Connector

(fan only, use in existing tray/bracket)
(HECI / CLEI: M3PQ0031AA)



NT7H72AA (HECI / CLEI: M3PQ0031AA)
WITH NEW FAN INSTALLED
(fan only, tray/bracket is not included)



INSIDE VIEW OF NORTEL OC12 CABINET
(4) FAN UNITS PICTURED HERE,
(8) TOTAL IN OC12 CABINETS

Ordering Information:

48V Fan for NT7H72AA found in Nortel OC12 Cabinets
w/ 2 Wire DB9M Connector
(fan only, use in existing tray/bracket) (HECI / CLEI: M3PQ0031AA)

FTR UPN #
TF-NTOC12-01

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

Telephone: (856) 753-8585
Fax : (856) 768-7645

www.tagcords.com

Telecom Assistance Group

Copyright © 2025 by Telecom Assistance Group, Inc.