

Litespan 2016 Cabinet Solutions

New Fan & Heat Exchanger Replacements

TAG # TF-LS2000-03

(NEW Replacement Heat Exchanger)



(6) HEAT EXCHANGERS
ROOF HX ASSEMBLY

TAG # TF-LS2000-44

(NEW Replacement DFA Fan Kit -
(4) New Fans per Kit)



Kit is shown installed
in existing DFA fan tray,
the tray IS NOT included

(4) "DFA" TRAYS ARE
SHOWN IN THIS CABINET
(4 KITS = 16 FANS)

TAG # TF-LS2000-02


(NEW Replacement Fan)




(2) "PDFA" TRAYS
ARE SHOWN IN THIS
CABINET (6 FANS)



LS2016 CABINET (OUTSIDE VIEW)



LS2016 CABINET (INSIDE - FRONT VIEW)



LS2016 CABINET (INSIDE - BACK VIEW)

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585
Fax : (856) 768-7645

Litespan 2016 Cabinet Solutions

New Fan & Heat Exchanger Replacements

<p>Ordering Information: TF-LS2000-03</p>	<p>48 Volt Replacement Heat Exchanger for Litespan 2016 Cabinet Roof HX Assembly w/ 3 Unterminated Leads - Red (+48 Return), Black (-48V), Blue (Sensor) <i>(includes (3) Butt Splices)</i></p>	
<p>TF-LS2000-44</p>	<p>DFA Fan Kit for Litespan 2016 Cabinet (4) NEW 48V Replacement Fans w/ Guard Grills <i>- includes (16) plastic rivets & (4) zip ties</i> (1) NEW Wiring Harness w/ 12 Wire Plug <i>use in existing DFA DC Fan Assembly 500-1100-XXX</i> <i>Individual fans (for splicing) can also be ordered, for a qty of (1) fan, order PN # TF-LS2000-04</i></p>	 <p><i>(fans only - tray is not included)</i></p>
<p>TF-LS2000-02</p>	<p>48 Volt Replacement Fan for Litespan 2016 Cabinet High Velocity PDFA Tray w/ 3 Wire Right Angle Connector <i>(includes plastic rivets)</i> <i>use in existing PDFA Fan Tray # 509-0000-XXX</i></p>	

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax : (856) 768-7645