
80 Type / SLC 2000 Cabinet Solutions for Verizon New Heat Exchanger, Fan & Alarm Control Replacements



150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (85

(856) 753-8585

Fax: (856) 768-7645

80 Type / SLC 2000 Cabinet Solutions for Verizon New Heat Exchanger, Fan & Alarm Control Replacements

Ordering Infor	mation:	
TF-SLC201-02	48V Heat Exchanger for 80 Type Cabinet w/ Screw on Connector (Equiv. to KS23912L4) (80 Type Cabinet - External)	Traccol 42 Service Bank Crac Inc. Wa (1)
TF-SLC201 <u>VZ ID #</u> 1132 1261	48V Fan for SLC 2000 4A / 4B Fan Trays w/ 5 Wire Plug (Equiv. to KS23912L6) (80 Type Cabinet, SLC 2000 Tray - Internal) (Replacement Power Cables for Lucent 4A/4B Fan Trays are available, order # TFCS-LU4APA-06 - call for pricing)	TF-BLC291 BY DOC BAIA TAG INC. WICE
TFC-114A-01	114A Fan Control Unit Replacement for 80 Type Cabinet Heat Exchangers (Equiv. to 106894934) (includes metal housing w/ alarm control board)	# TFC-114A-01 # TFC-LU4-01
TFC-LU4-01	Alarm Control Board Replacement for Lucent 4A/4B, 4G/SLC 2000 Fan Trays & 114A Control Units (control board only - customer supplied fan trays / 114A housing)	
TF-SLCBC-01	48V Cooling Fan for 80 Type Cabinet Battery Compartment w/ 3 Wire Plug	# TF-SLCBC-01 # TFC-116A-01
TFC-116A-01	Alarm Control Board for Lucent 116A Battery Fan Unit (control board only - customer supplied metal housing)	

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585 Fax: (856) 768-7645