
Litespan 2016 Cabinet Solutions for Verizon

New Heat Exchangers, Fans & Alarm Control Replacements



150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585 Fax: (856) 768-7645

1 dx : (050) 100-1040

Litespan 2016 Cabinet Solutions for Verizon

New Heat Exchangers, Fans & Alarm Control Replacements

Ordering Information:		
TF-LS2000-03 VZ ID # 1132 9780	48V Heat Exchanger for Litespan 2016 Cabinet Roof HX Assembly w/ 3 Unterminated Leads - Red (+48 Return), Black (-48V), Blue (Sensor) Includes (3) Butt Splices	TF-LS2000-03 46V=DC 35W 0.72A RETURN TAG INC. TAG INC. SENSOR
TF-LS2000-44 <u>VZ ID #</u> 1136 1758	Litespan 2000 DFA Fan Kit (4) NEW 48V Fans w/ Guard Grills (1) NEW Wiring Harness w/ 12 Wire Plug use in existing DFA DC Fan Assembly # 500-1100-XXX Individual fans (for splicing) can also be ordered, for a qty of (1) fan, order PN # TF-LS2000-04, VZ ID # 1136 1757	(fans only - tray is not included)
TFC-DFA-01 7501 3160	Alarm Control Board for Litespan DFA Fan Trays use in existing DFA DC Fan Assembly # 500-1100-XXX	TFCOFA01 TGGINC TAGINC THE
TFC-PDFA-01 7500 8240	Alarm Control Board for Litespan High Velocity PDFA Fan Trays use in existing High Velocity PDFA Fan Assemblies # 509-0000-086/163	TFC-DFA-01 TFC-PDFA-01 (DFA Alarm Control) (HV PDFA Alarm Control)
TF-LS2000-02 <u>VZ ID #</u> 1132 7455	48V Fan for Litespan 2016 Cabinet High Velocity PDFA Tray w/ 3 Wire Connector (includes plastic rivets) use in existing High Velocity PDFA Fan Assemblies # 509-0000-086/163	TF-LS2000-02 48Y-DC 3W 0.73A BIRT MAX-64 B

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585 Fax: (856) 768-7645