


Heat Exchangers

TAG # TF-SLC201-02
(NEW Heat Exchanger)

Lumen/CLK MAT # 1337731

(2) MOUNTED
ON CABINET SIDE
(TOP & BOTTOM)



TAG # TFC-LU4-01

(NEW Alarm Control Board)

Lumen/CLK MAT # 1355244

(1) ALARM BOARD
PER TRAY

4A / 4B Fan Trays



TAG # TF-SLC201 (NEW 48V Fan)

Lumen/CLK MAT # 1336047

(2) FAN TRAYS SHOWN
IN THIS CABINET
(4 FANS TOTAL)

Fans are shown installed
in existing fan tray,
the tray IS NOT included

(NEW Power Cables
for 4A/4B Fan Trays
are available, order
TFCS-LU4APA-06)



116A
Control Unit
(Battery)
- reverse side
of cabinet

114A Control Unit





TAG # TFC-114A-01*

(NEW Heat Exchanger
Control Unit)

Lumen/CLK MAT # 1355243

* if metal housing is not needed,
order # TFC-LU4-01
Lumen/CLK MAT # 1355244



116A Board


(1) PER CABINET

TAG # TFC-116A-01

(NEW Alarm Control Board
for Lucent 116A Battery Unit)

Lumen/CLK MAT # 1459078

80 TYPE CABINET
(INSIDE VIEW)



TAG # TF-SLCBC-01

(NEW Battery Cooling Fan)

(1) FAN PER CABINET

Lumen/CLK MAT # 1461343

Battery Cooling










150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax: (856) 768-7645

Ordering Information:			
<p>TF-SLC201-02</p> <p>MAT # 1337731</p>	<p>48V Heat Exchanger for 80 Type Cabinet w/ Screw on Connector</p> <p><i>(Equiv. to KS23912L4)</i></p> <p><i>(80 Type Cabinet - External)</i></p>	 	
<p>TF-SLC201</p> <p>MAT # 1336047</p>	<p>48V Fan for SLC 2000 4A / 4B Fan Trays w/ 5 Wire Plug</p> <p><i>(Equiv. to KS23912L6)</i></p> <p><i>(80 Type Cabinet, SLC 2000 Tray - Internal)</i></p> <p><i>(Replacement Power Cables for Lucent 4A/4B Fan Trays are available, order # TFCS-LU4APA-06 - call for pricing)</i></p>	 	
<p>TFC-114A-01</p> <p>MAT # 1355243</p>	<p>114A Fan Control Unit Replacement for 80 Type Cabinet Heat Exchangers <i>(Equiv. to 106894934)</i></p> <p><i>(includes metal housing w/ alarm control board)</i></p>	<p># TFC-114A-01</p> 	<p># TFC-LU4-01</p> 
<p>TFC-LU4-01</p> <p>MAT # 1355244</p>	<p>Alarm Control Board Replacement for Lucent 4A/4B, 4G/SLC 2000 Fan Trays & 114A Control Units</p> <p><i>(control board only - customer supplied fan trays / 114A housing)</i></p>		
<p>TF-SLCBC-01</p> <p>MAT # 1461343</p>	<p>48V Cooling Fan for 80 Type Cabinet Battery Compartment w/ 3 Wire Plug</p>	<p># TF-SLCBC-01</p>  	<p># TFC-116A-01</p> 
<p>TFC-116A-01</p> <p>MAT # 1459078</p>	<p>Alarm Control Board for Lucent 116A Battery Fan Unit</p> <p><i>(control board only - customer supplied metal housing)</i></p>		

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax : (856) 768-7645