36B Cabinet Solutions

New Replacement Fans & Accessories



TAG # T-6W3F-05

(NEW Replacement Protector / 526A to 125 Station Protector)

(1) IN EACH CABINET




(NEW Replacement Fan)

(1) FAN TRAY UNIT IN EACH CABINET (3 FANS)





36B CABINET (OUTSIDE VIEW)



INSIDE VIEW OF CABINET



2C FAN TRAY UNIT (SIDE VIEW)

150 Cooper Rd. (F-15) W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone:

(856) 753-8585

AIRFLOW DIRECTION ON (3) FANS **POINT UP**

Fax:

(856) 768-7645

36B Cabinet Solutions

New Replacement Fans & Accessories

Ordering Information: TF-LU2C	48 Volt Replacement Fan for Lucent 2C Fan Tray w/ 3 Wire Plug (Equiv. to KS22501L5A) (36B Cabinet, Lucent 2C Tray - Internal)	TF-LU2C ASV:=DC 0.38A TAG INC. TAG INC. TAG INC.
T-6W3F-05	Protector / 526A plug to 125 Station Protector (5') - available in various lengths (36B Cabinet, Test Cord - Internal) • Cabinet mounting assembly for performing line tests on SLC-96 & Series 5	125 Station Protector (5') 463A 526A

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585 Fax: (856) 768-7645

datasheets\Fans\OSP Cabinet\Lucent\TAG_36B_Cabinet_Solutions_r03.dsf (03/21/23)