
## **Litespan 2016 Cabinet Solutions**

## New Heat Exchangers, Fans & Alarm Control Replacements



Copyright © 2023 by Telecom Assistance Group, Inc.

datasheets\Fans\OSP Cabinet\Alcatel\TAG\_LS2016\_Cabinet\_Solutions\_r04.dsf (03/21/23)

## **Litespan 2016 Cabinet Solutions**

## New Heat Exchangers, Fans & Alarm Control Replacements

Ordering Information:		
TF-LS2000-03	48V Heat Exchanger for Litespan 2016 Cabinet Roof HX Assembly w/ 3 Unterminated Leads - Red (+48 Return), Black (-48V), Blue (Sensor) Includes (3) Butt Splices	THISOBOAL THIS BORN THE SAME THE
TF-LS2000-44	Litespan 2000 DFA Fan Kit   (4) <u>NEW</u> 48V Fans w/ Guard Grills   (1) <u>NEW</u> Wiring Harness w/ 12 Wire Plug   use in existing DFA DC Fan Assembly # <u>500-1100-XXX</u> Individual fans (for splicing) can also be ordered, for a qty of (1) fan, order # TF-LS2000-04	(fans only - tray is not included)
TFC-DFA-01	Alarm Control Board for Litespan DFA Fan Trays use in existing DFA DC Fan Assembly # <u>500-1100-XXX</u>	
TFC-PDFA-01	Alarm Control Board for Litespan High Velocity PDFA Fan Trays use in existing High Velocity PDFA Fan Assemblies # <u>509-0000-086/163</u>	TFC-DFA-01   TFC-PDFA-01     (DFA Alarm Control)   (HV PDFA Alarm Control)
TF-LS2000-02	<b>48V Fan for Litespan 2016 Cabinet High Velocity PDFA Tray</b> w/ 3 Wire Connector ( <i>includes plastic rivets</i> ) use in existing High Velocity PDFA Fan Assemblies # <u>509-0000-086/163</u>	TF-LS200-02 W-TO-C 30% 07.4 TAG INC. TAG INC. TAG INC. TAG INC.
0 Cooper Rd. ( . Berlin, NJ  08		Telephone: (856) 753-85 DUP Fax : (856) 768-76

Copyright © 2023 by Telecom Assistance Group, Inc.

datasheets\Fans\OSP Cabinet\Alcatel\TAG\_LS2016\_Cabinet\_Solutions\_r04.dsf (03/21/23)