Litespan 2000 (LSC-2020) Cabinet Solutions


New Heat Exchangers, Fans & Alarm Control Replacements

TAG # TF-LS2000-44

(NEW Replacement DFA Fan Kit -

(4) New Fans per Kit)

(3) TRAYS ARE SHOWN IN THIS CABINET (3 KITS = 12 FANS)



Kit is shown installed in existing DFA fan tray, the tray IS NOT included



TAG # TFC-DFA-01

(NEW Replacement DFA Alarm Control Board)

(1) ALARM BOARD PER TRAY




TAG # TF-LS2000-03

(NEW Replacement Heat Exchanger)

(2) IN EACH HEAT STACK (TOP & BOTTOM)



LSC-2020 CABINET (OUTSIDE VIEW)



LSC-2020 CABINET (INSIDE - FRONT VIEW)

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax: (856) 768-7645

Ordering Information:		
TF-LS2000-03	48V Heat Exchanger for Litespan 2000 Cabinet Heat Stack w/ 3 Unterminated Leads - Red (+48 Return), Black (-48V), Blue (Sensor) Includes (3) Butt Splices	TF-LS2000-03 A0Y==DC SW 0.72A RN-44F MLX-44V RLC HWIST SAME TAG INC. SIGN-374-48 RL C C MI C C S
TF-LS2000-44	Litespan 2000 DFA Fan Kit (4) NEW 48V Fans w/ Guard Grills - includes (16) plastic rivets & (4) zip ties (1) NEW Wiring Harness w/ 12 Wire Plug use in existing DFA DC Fan Assembly 500-1100-XXX Individual fans (for splicing) can also be ordered, for a qty of (1) fan, order PN # TF-LS2000-04	(fans only - tray is not included)
TFC-DFA-01	Alarm Control Board for Litespan 2000 DFA Fan Trays use in existing DFA DC Fan Assembly 500-1100-XXX	TEC.DEA.01 TAG INC. include: incl

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax: (856) 768-7645