



5ESS Replacement Fans (KS23912L1A Models)

KS23912L1A Models



PN # TF-5ESS-02P
5ESS Replacement Fan
 w/ 5 Leads & AMP Connector

VZ ID # 1129 4862



PN # TF-5ESS-02F
5ESS Replacement Fan
 w/ 5 Leads & Faston Connectors

VZ ID # 1129 4863



Application:

TAG's PN #'s TF-5ESS-02P and TF-5ESS-02F replace defective 48 Volt, KS23912L1A type 5ESS switch fans with internal thermal speed control sensor.

Ordering Information:

		VZ ID #
TF-5ESS-02P	5ESS Replacement Fan (KS23912L1A) w/ 5 Leads and AMP Connector <i>(w/ Internal Thermal Speed Control Sensor)</i>	1129 4862
TF-5ESS-02F	5ESS Replacement Fan (KS23912L1A) w/ 5 Leads and Faston Connectors <i>(w/ Internal Thermal Speed Control Sensor)</i>	1129 4863

150 Cooper Rd. (F-15)
 W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
 Fax : (856) 768-7645

Telecom Assistance Group