

## OSP Cabinet Replacement Fans

### "Litespan PDFA"




**AT&T PID #**  
**ATT.200002982**

**PDFA FAN ASSEMBLY,  
FAN TRAY # 500-1126-723**



*(fan tray is not included)*



**PN # TF-LS2000-01**

48 Volt Replacement Fan for  
**Litespan 2000 Power Distribution (PDFA)**


w/ 3 Wire Plug & Guard Grill  
(includes plastic rivets)

**PN # TF-LS2000-02**

48 Volt Replacement Fan for  
**Litespan 2000 High Velocity PDFA**

w/ 3 Wire Right Angle Connector  
(includes plastic rivets)

**HIGH VELOCITY PDFA FAN ASSEMBLY,  
FAN TRAY # 509-0000-086**  
*(fan tray is not included)*



**TRAY w/ (3) NEW  
TAG FANS INSTALLED**

### "Litespan High Velocity PDFA"



**AT&T PID #**  
**ATT.200002983**

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585  
Fax : (856) 768-7645

**Telecom Assistance Group**