

OSP Cabinet Replacement Salt Air Door Fan Tray

"CommScope ALP 448/248"

PN # TFT-COM48B-01


**3 Fan Stainless Steel Assembly for
CommScope ALP 448/248 HX Door Fans**

*(Replacement for HX FAN ASSY:
CMMI860481399)*



COMMSCOPE ALP 448/248 CABINET

Replace RUSTY Fan Assemblies Caused by SALT AIR



Ordering Information:

TFT-COM48B-01

3 Fan Stainless Steel Assembly for CommScope ALP 448/248 HX Door Fans
includes: (3) NEW 48V FANS (# TF-COM6DF-02B, w/ 5 Wire, 6 Pin Connectors) & Grommet

AT&T PID #

ATT.200010349

TFT-COM48B-02

Stainless Steel Plate for CommScope ALP 448/248 HX Door Fans (plate only)

ATT.200010350

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax : (856) 768-7645