


SLC 2000 Cabinet Solutions

New Fans & Alarm Control Board/Unit Replacements

External Fans

TAG # TF-SLC201-02


(NEW Replacement Heat Exchanger)



4A / 4B Fan Trays

TAG # TFC-LU4-01

(NEW Replacement Alarm Control Board)



TAG # TF-SLC201

(NEW Replacement Fan)



SLC 2000 CABINET (EXTERNAL)



SLC 2000 CABINET (INTERNAL)

114A Control Unit



TAG # TFC-114A-01*

(NEW Replacement Fan Control Unit)

** if metal housing is not needed, order # TFC-LU4-01*







150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585
Fax : (856) 768-7645

SLC 2000 Cabinet Solutions

New Fans & Alarm Control Board/Unit Replacements

Ordering Information: TF-SLC201-02	SLC 2000 Cabinet 48 Volt Replacement Heat Exchanger w/ Screw on Connector <i>(Equiv. to KS23912L4)</i> <i>(SLC 2000 Cabinet - External)</i>	 
TFC-114A-01	114A Fan Control Unit Replacement for SLC 2000 Cabinet Heat Exchangers <i>(includes metal housing w/ alarm control board)</i> <i>(Equiv. to 106894934)</i>	 <p>114A Replacement Unit w/ Alarm Control Board</p>
TFC-LU4-01	Alarm Control Board Replacement for Lucent 4A / 4B, 4G / SLC2000 Fan Trays & 114A Control Units <i>(customer supplied fan trays / 114A housing)</i>	
TF-SLC201	SLC 2000 Cabinet 48 Volt Replacement Fan w/ 5 Wire Plug <i>(Equiv. to KS23912L6, use in Lucent <u>4A / 4B</u> fan unit)</i> <i>(SLC 2000 Cabinet - Internal)</i>	 

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax : (856) 768-7645