

OSP Cabinet Replacement Fans & Alarm Control Boards


"Litespan High Velocity PDFA"




PN # TF-LS2000-02
48 Volt Replacement Fan for
Litespan 2000 OSP High Velocity PDFA

(Round Fan)
w/ 3 Wire Connector
(includes plastic rivets)

HIGH VELOCITY PDFA FAN ASSEMBLY,
FAN TRAY # 509-0000-086 / 509-0000-163
(fan tray is not included)



NEW Alarm Control Boards
are also available,
order # **TFC-PDFA-01**



Ordering Information:

TF-LS2000-02	48 Volt Replacement Fan for Litespan 2000 OSP High Velocity PDFA (Round Fan) w/ 3 Wire Connector	Call for Pricing
	<i>(includes plastic rivets) (use in High Velocity PDFA Fan Tray # 509-0000-086 / 509-0000-163)</i>	

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group