Litespan 2000 (LSC-2020) Cabinet Solutions


New HX, Fans & Alarm Control Replacements

TAG # TF-LS2000-44

(NEW DFA Fan Kit - (4) New Fans per Kit)

MAT # 1445489

(3) TRAYS ARE SHOWN IN THIS CABINET (3 KITS = 12 FANS)



Kit is shown installed in existing DFA fan tray, the tray IS NOT included



TAG # TFC-DFA-01

(NEW DFA Alarm Control Board)

MAT # 1458948

(1) ALARM BOARD PER TRAY



TAG # TF-LS2000-03


(NEW Heat Exchanger)

MAT # 1359389

(2) IN EACH
HEAT STACK
(TOP & BOTTOM)



LSC-2020 CABINET (OUTSIDE VIEW)



LSC-2020 CABINET (INSIDE - FRONT VIEW)

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (8

ne: (856) 753-8585 x : (85<u>6) 768-7645</u>

Fax: (856) 768-7645

Ordering Information:

TF-LS2000-03

MAT # 1359389

48V Heat Exchanger for Litespan 2000 Cabinet Heat Stack

w/ 3 Unterminated Leads -Red (+48 Return), Black (-48V), Blue (Sensor)

Includes (3) Butt Splices



TF-LS2000-44

MAT # 1445489

Litespan 2000 DFA Fan Kit

- (4) NEW 48V Fans w/ Guard Grills - includes (16) plastic rivets & (4) zip ties
- (1) NEW Wiring Harness w/ 12 Wire Plug use in existing DFA DC Fan Assembly 500-1100-XXX

Individual fans (for splicing) can also be ordered, for a gty of (1) fan. order # TF-LS2000-04, MAT # 1445620



(fans only - tray is not included)

TFC-DFA-01

MAT # 1458948

Alarm Control Board for Litespan 2000 DFA Fan Trays

use in existing DFA DC Fan Assembly 500-1100-XXX



150 Cooper Rd. (F-15) W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone:

(856) 753-8585

Fax: (856) 768-7645