

OSP Cabinet Replacement Fans & Alarm Control Boards

"Litespan PDFA"



MAT # 1341519


PN # TF-LS2000-01
48 Volt Replacement Fan for
Litespan 2000 Power Distribution (PDFA)
w/ 3 Wire Plug & Guard Grill (includes plastic rivets)

USE IN FAN TRAY # 500-1126-723
(fan tray is not included)

NEW Alarm Control Boards
are also available,
order # **TFC-PDFA-X2**



*(2 ALARM CONTROL BOARDS
ARE USED IN EACH TRAY)*




PN # TF-LS2000-02
48 Volt Replacement Fan for
Litespan 2000 High Velocity PDFA
w/ 3 Wire Connector
(includes plastic rivets)

"Litespan High Velocity PDFA"



NEW Alarm Control Boards
are also available,
order # **TFC-PDFA-01**



MAT # 1356400

HIGH VELOCITY PDFA FAN ASSEMBLY,
FAN TRAY # 509-0000-086 / 509-0000-163
(fan tray is not included)

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group