OSP Cabinet Replacement Fans & Alarm Control Boards

"Lucent 4A / 4B"

PN # TF-SLC201

48 Volt Replacement Fan for SLC 2000 4A / 4B Fan Trays

w/ 5 Wire Plug

(Equiv. to KS23912L6)

(80 Type Cabinet, SLC 2000 Tray - Internal)

SLC 2000 EQUIPMENT - 4B FAN UNIT w/ (2) FANS

(fan tray is not included)





NEW Alarm Control Boards are also available, order #TFC-LU4-01



Ordering Information:

Brightspeed MAT #

TF-SLC201 48V Fan w/ 5 Wire Plug for SLC 2000 4A / 4B Fan Trays 1336047

(Equiv. to KS23912L6) (80 Type Cabinet, SLC 2000 Tray - Internal)

TFC-LU4-01 Alarm Control Board Replacement for 4A/4B,

4G/SLC 2000 Trays & 114A Control Units

(control board only - customer supplied fan trays / 114A housing)

MAT # 1355244

150 Cooper Rd. (F-15) W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585

Fax: (856) 768-7645

Telecom Assistance Group