

# 80 Type / SLC 2000 Cabinet Solutions for AT&T

# New Heat Exchanger, Fan & Alarm Control Replacements

## Heat Exchangers

**TAG # TF-SLC201-02**  
**AT&T PID # ATT.200002995**  
 (NEW Heat Exchanger)


**(2) MOUNTED ON CABINET SIDE (TOP & BOTTOM)**




**TAG # TFC-LU4-01**  
**AT&T PID # ATT.200004557**  
 (NEW Alarm Control Board)

**(1) ALARM BOARD PER TRAY**

## 4A / 4B Fan Trays



**TAG # TF-SLC201** (NEW 48V Fan)

**AT&T PID # ATT.200002993**


**(2) FAN TRAYS SHOWN IN THIS CABINET (4 FANS TOTAL)**

Fans are shown installed in existing fan tray, **the tray IS NOT included**

(NEW Power Cables for 4A/4B Fan Trays are available, order # **TFCs-LU4APA-06** AT&T PID # **ATT.200008566**)



**116A Control Unit (Battery)**  
 - reverse side of cabinet




**116A Board**  
**(1) PER CABINET**



**TAG # TF-SLCBC-01**  
**AT&T PID # ATT.200006505**  
 (NEW Battery Cooling Fan)

**(1) FAN PER CABINET**

**Battery Cooling**

**TAG # TFC-116A-01**  
**AT&T PID # ATT.200006502**  
 (NEW Alarm Control Board for Lucent 116A Battery Unit)

**80 TYPE CABINET (INSIDE VIEW)**

## 114A Control Unit



**TAG # TFC-114A-01\***

**AT&T PID # ATT.200006506**

(NEW Heat Exchanger Control Unit)

\* if metal housing is not needed,

order # **TFC-LU4-01**



**AT&T PID # ATT.200004557**

150 Cooper Rd. (F-15)  
 W. Berlin, NJ 08091

www.tagcords.com  
**Telecom Assistance Group**

Telephone: (856) 753-8585  
 Fax: (856) 768-7645

**Ordering Information:**

<p>TF-SLC201-02</p> <p><b>AT&amp;T PID #</b> <b>ATT.200002995</b></p>	<p><b>48V Heat Exchanger for 80 Type Cabinet w/ Screw on Connector</b></p> <p><i>(Equiv. to KS23912L4)</i> <i>(80 Type Cabinet - External)</i></p>	
<p>TF-SLC201</p> <p><b>AT&amp;T PID #</b> <b>ATT.200002993</b></p>	<p><b>48V Fan for SLC 2000 4A / 4B Fan Trays w/ 5 Wire Plug</b></p> <p><i>(Equiv. to KS23912L6)</i> <i>(80 Type Cabinet, SLC 2000 Tray - Internal)</i></p> <p><i>(Replacement Power Cables for Lucent 4A/4B Fan Trays are available, order # TFCS-LU4APA-06, AT&amp;T PID # ATT.200008566)</i></p>	
<p>TFC-114A-01</p> <p><b>AT&amp;T PID #</b> <b>ATT.200006506</b></p>	<p><b>114A Fan Control Unit Replacement for 80 Type Cabinet Heat Exchangers</b> <i>(Equiv. to 106894934)</i></p> <p><i>(includes metal housing w/ alarm control board)</i></p>	 <p># TFC-114A-01</p> <p># TFC-LU4-01</p>
<p>TFC-LU4-01</p> <p><b>AT&amp;T PID #</b> <b>ATT.200004557</b></p>	<p><b>Alarm Control Board Replacement for Lucent 4A/4B, 4G/SLC 2000 Fan Trays &amp; 114A Control Units</b></p> <p><i>(control board only - customer supplied fan trays / 114A housing)</i></p>	
<p>TF-SLCBC-01</p> <p><b>AT&amp;T PID #</b> <b>ATT.200006505</b></p>	<p><b>48V Cooling Fan for 80 Type Cabinet Battery Compartment w/ 3 Wire Plug</b></p>	 <p># TF-SLCBC-01</p> <p># TFC-116A-01</p>
<p>TFC-116A-01</p> <p><b>AT&amp;T PID #</b> <b>ATT.200006502</b></p>	<p><b>Alarm Control Board for Lucent 116A Battery Fan Unit</b></p> <p><i>(control board only - customer supplied metal housing)</i></p>	

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

**Telecom Assistance Group**

Telephone: (856) 753-8585

Fax: (856) 768-7645