| | Verizon | | Pa |
|--|----------------------|---------------|--|
| FEATURES / APPLICATION | PART # | VZ ID # | DESCRIPTION |
| Bantam to Bantam - Red, (6') | 400210RD | 1104 3640 | BANTAM to BANTAM - RED |
| Bantam to Bantam - Red, (3') | 400210RD-03 | 1100 7946 | |
| Bantam to Bantam - Red, (8') | 400210RD-08 | 1100 7947 | ¢1 |
| Bantam to Bantam - Red, (13') | 400210RD-13 | 1125 8962 | |
| General purpose test / patch cord | | | |
| Bantam to Bantam - Black, (6') | 400210BK | 1104 3639 | BANTAM to BANTAM - BLACK |
| Bantam to Bantam - Black, (3') | 400210BK-03 | 1100 7943 | |
| Bantam to Bantam - Black, (8') | 400210BK-08 | 1100 7944 | d1 |
| Bantam to Bantam - Black, (13') | 400210BK-13 | 1125 8963 | |
| General purpose test / patch cord | | | |
| Bantam to Bantam, (6') | 400210 | 8721 4240 | BANTAM to BANTAM |
| Bantam to Bantam, (2') | 400210-02 | 8727 2187 | |
| Bantam to Bantam, (4') | 400210-04 | 8727 3292 | |
| Bantam to Bantam, (10') | 400210-10 | 8725 7313 | |
| Bantam to Bantam, (12') | 400210-12 | 8724 0825 | |
| Bantam to Bantam, (15') | 400210-15 | 8727 3294 | |
| Bantam to Bantam, (20') | 400210-20 | 8723 6197 | |
| Bantam to Bantam, (25') | 400210-25 | 8727 4263 | |
| Bantam to Bantam, (30') | 400210-30 | 8722 2495 | |
| Bantam to Bantam, (40') | 400210-40 | 8726 0958 | |
| Bantam to Bantam, (50') | 400210-50 | 1105 1326 | |
| General purpose test / patch cord | | | |
| Right Angle Bantam to Right Angle Bantam, (2') | 400210R | 363418 | RIGHT ANGLE PATCH CORD |
| Right Angle 310 to Right Angle 310, (2') | 400310R | 8703 1754 | |
| | | | |
| "Right Angle" test cord for "Patching" T1 circuits inside | e SLC Series 5 or SL | C-96 cabinets | |
| ght © 2024 by Telecom Assistance Group, Inc. Iecom Assistance Group (TAG) | 150 Cooper R | d. (F-15) | 2024 Verizon ID\Master\02vz_r24.dsf (0 Telephone: (856) 753-8 |
| ww.tagcords.com | W. Berlin, NJ 08091 | | Fax: (856) 768-7 |