

Alcatel 1631* Replacement Fans

PN # TF-ALC1631-01
 48V Replacement Fan for
Alcatel 1631 Blower Assembly
 w/ Power Prongs

AT&T PID #
ATT.200006515



"Alcatel 1631"



(fan only -
 use with
 existing
 guard grill)

← **# 695-3363-302 (w/ 3 EXISTING FANS)**
 (blower assembly is not included)

"Alcatel 1631"

(fan only -
 use with
 existing
 guard grill)



AT&T PID #
ATT.200004402

PN # TF-ALC1631-02
 48V Replacement Fan for
Alcatel 1631 Blower Assembly
 w/ Power Prongs,
 Unterminated Tach Lead & (1) Butt Splice




3AL45446AA (w/ 3 EXISTING FANS)
 (blower assembly is not included)

PN # TF-ALC1631-03
 48V Replacement Fan for
Alcatel 1631 APS Blower Assembly

w/ Power Prongs &
 Unterminated Tach Lead


AT&T PID #
ATT.200009343



"Alcatel 1631"



(fan only -
 use with existing
 guard grill)



← **# 695-8489-001 (w/ 3 EXISTING FANS)**
 (blower assembly is not included)

150 Cooper Rd. (F-15)
 W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
 Fax : (856) 768-7645

Telecom Assistance Group