



Carrier VoIP Replacement Fans



AT&T PID #
ATT.200008577




FRONT VIEW OF →
NTLX56AA FAN ASSEMBLY
(NOT SUPPLIED)

"Nortel IW SPM-IP"

PN # TF-DMS-FOS
Nortel IW SPM-IP
48 Volt Replacement Fan
for **NTLX56AA** fan assemblies*

used in **Nortel IW SPM-IP NTLX55AA** cooling units


* fan only, arm assembly is not included



"Media Gateway 9000"

PN # TF-MG9K-01
Nortel / GENBAND Media Gateway 9000
48 Volt Replacement Fan

w/ 3 Wire Plug
(for use in **NTNY18AA** Cooling Unit)



AT&T PID #
ATT.200008585

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group