

Identifying Lucent 114A Fan Control Units

(COMCODE: 106894934)



TAG Refurbishment, Fan Control 114A (TFR-114A-01)

Fan Control 114A
(COMCODE: 106894934)



Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit. The Ship To Address is required. It will be the address that the unit will be returned to. Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

Tool/Test Set: Fan Assembly, 114A Lucent Control Unit for Heat Exchanger Fans (COMCODE: 106894934) TAG Refurbishment TFR-114A-01

Supplier: TAG INC. (TAG is chosen as the supplier)

Serial Number:

Asset Tag:

Ship to Address: 1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044 [Lookup](#)

Manager ATTUID (Who Owns Equipment): RS781D [Lookup](#)

Contact ATTUID (To Be Called if Problem): RS781D

Problem Category: Other

Description of Problem: Refurbish 114A fan control unit

Manufacturer: Lucent

Model #: 114A fan control unit

Create Ticket will issue repair # and shipping label

Main Menu | Order Material | My Orders | My Approvals | My Material | Order Status | Reports | Profile | View Cart | Help | Logout | © AT&T Inc.

upFront Tool

Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

http://procurement05.web.att.com/labelmaker/TestSetsLabel.asp?id=135580 - Internet Explorer provided by AT&T

Repair Return Label #135580

Repair Tag: R735580  **SAMPLE**

Truck Route (GA005A): 

Return To: SOPHIA ADAMS
1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044

Telephone: 4044996083

Product Description: NOT LISTED: ALL Other Non-Tool/Test Not listed in Category below

Serial Number

Asset Tag

RMA

Problem Category: Intermittent Problem

Description of Problem: THE UNIT FAILS TO OPERATE AFTER 5 MINUTES.

SHIP MATERIAL TO:

Stage for RYDER pickup and delivery to Team Alliance Drop Code: GA005A

Print Date: 2/19/2016 8:00:08 AM
Supplier Website for More Detail: http://www.attsuppliers.com