


Identifying Ciena 5140 Fan Assemblies



TAG Refurbishment, Ciena 5140 Fan Assembly (TFR-CN5140-01)



Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit. The Ship To Address is required. **It will be the address that the unit will be returned to.** Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

TAG is chosen as the supplier

Create Ticket will issue repair # and shipping label

Tool/Test Set: Fan Assembly, Ciena 5140 Fan Tray TAG Refurbishment TFR-CN5140-01
 Supplier: TAG INC.
 Serial Number:
 Asset Tag:
 Ship to Address: 1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044 [Lookup](#)
 Manager ATTUID (Who Owns Equipment): RS781D [Lookup](#)
 Contact ATTUID (To Be Called if Problem): RS781D
 Problem Category: Other
 Description of Problem: Refurbish Ciena 5140 Fan Assembly
 Manufacturer: Ciena
 Model #: 5140 Fan Assembly

[Main Menu](#) | [Order Material](#) | [My Orders](#) | [My Approvals](#) | [My Material](#) | [Order Status](#) | [Reports](#) | [Profile](#) | [View Cart](#) | [Help](#) | [Logout](#) | © AT&T Inc.

upFront Tool

Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

http://procurement05.web.att.com/labelmaker/TestSetsLabel.asp?id=135580 - Internet Explorer provided by AT&T

Repair Return Label #135580

Repair Tag:	R735580		SAMPLE
Truck Route (GA005A):			
Return To	SOPHIA ADAMS 1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044		
Telephone	4044996083		
Product Description	NOT LISTED: ALL Other Non-Tool/Test Not listed in Category below		
Serial Number			
Asset Tag			
RMA			
Problem Category	Intermittent Problem		
Description of Problem	THE UNIT FAILS TO OPERATE AFTER 5 MINUTES.		

SHIP MATERIAL TO:

Stage for RYDER pickup and delivery to Team Alliance Drop Code: GA005A

Print Date: 2/19/2016 8:00:08 AM
Supplier Website for More Detail: <http://www.attsuppliers.com>