Rectifier TAG, LORAIN LXP1750 Power Supply Repair TRR-LXP1750



Tool and Test Set Repair Ticket Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit. The Ship To Address is required. It will be the address that the unit will be returned to. Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed. TAG's Fan Assembly refurbishment item is chosen	
	from the dropdown menu
Tool/Test Set	Rectifier TAG, LORAIN LXP1750 Power Supply Repair TRR-LXP1750
Supplier	TAG INC.
Serial Number Asset Tag	TAG is chosen as the supplier
•	1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044 Lookup
Ship to Address	
Manager ATTUID (Who Owns Equipment)	RS781D Lookup
Contact ATTUID (To Be Called if Problem)	RS781D
Problem Category	Other •
Description of Problem	FAILED UNIT
Manufacturer	LORAIN Cooper Tieles will in our remain # and
Model #	Create Ticket will issue repair # and shipping label
Main Menu Order Material My Ord	Create Ticket Repair Menu ders My Approvals My Material Order Status Reports Profile View Cart Help Logout © AT&T Inc.
Main Mend Order Material My Ore	The state of the s

upFront Tool

Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print (3) three copies, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.



AT&T is a registered ® trademark