


TAG Refurbishing - Lorain, V100BR Ring Generator

- Replace Fans & Necessary Components

Repair Benefits:

- Save Engineering \$\$ on new OSP equipment
- Ease of Replacement "Swap out"



**HECI / CLEI:
PRPUAF01AA**



Ordering Information:

TRR-RGV100BR Ring Generator TAG, LORAIN V100BR Ring Generator
TRR-RGV100BR

**V100BR RING GENERATOR REFURBISHMENTS
ARE NOW AVAILABLE IN AT&T UPFRONT**

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585
Fax: (856) 768-7645

Ring Generator TAG, LORAIN V100BR Ring Generator TRR-RGV100BR



Tool and Test Set Repair Ticket

Please complete the form below. If possible, include the Serial Number/Asset Tag of the unit.
The Ship To Address is required. **It will be the address that the unit will be returned to.**
Upon submission, a shipping label will be generated. This must be included on your return. You will be notified via email when the equipment is received by the Supplier and when the Repair has been completed.

TAG's Fan Assembly refurbishment item is chosen from the dropdown menu

Tool/Test Set: Ring Generator TAG, LORAIN V100BR Ring Generator TRR-RGV100BR

Supplier: TAG INC. **TAG is chosen as the supplier**

Serial Number:

Asset Tag:

Ship to Address: 1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044 [Lookup](#)

Manager ATTUID (Who Owns Equipment): RS781D [Lookup](#)

Contact ATTUID (To Be Called if Problem): RS781D

Problem Category: Other

Description of Problem: FAILED UNIT

Manufacturer: LORAIN

Model #: V100BR

Create Ticket will issue repair # and shipping label

Main Menu | Order Material | My Orders | My Approvals | My Material | Order Status | Reports | Profile | View Cart | Help | Logout | © AT&T Inc.

upFront Tool

Repair Return Label

Once the ticket has been created and submitted, if successful, the user will receive a **Repair Tag Number** and shipping document as shown in the example below.

- Please print **(3) three copies**, this allows the user to keep one, place one inside the box, and place one outside the box when shipping your tool/material for repair.
- Once you have completed printing all of your copies you can exit out of the Repair Return Label screen.

http://procurement05.web.att.com/labelmaker/TestSetsLabel.asp?id=135580 - Internet Explorer provided by AT&T

Repair Return Label #135580

Repair Tag: R735580

Truck Route (GA005A):

Return To: SOPHIA ADAMS
1311 PROVIDENCE DR, LAWRENCEVILLE, GA 30044
30044

Telephone: 4044996083

Product Description: NOT LISTED: ALL Other Non-Tool/Test Not listed in Category below

Serial Number: 123456

Asset Tag: abcde####

RMA

Problem Category: Intermittent Problem

Description of Problem: THE UNIT FAILS TO OPERATE AFTER 5 MINUTES.

SAMPLE

SHIP MATERIAL TO:

TAG, Inc. (Telecom Assistance Group)
150 Cooper Rd. Suite F-15
West Berlin, NJ 08091

Print Date: 7/19/2024 1:39:32 PM
Supplier Website for More Detail: <http://www.attsuppliers.com>