


# TAG Refurbishing - Lorain, LXP1500 Rectifier Power Supply

- Replace Fan & Necessary Components

## Repair Benefits:

- Save Engineering \$\$ on new OSP equipment
- Ease of Replacement "Swap out"



**HECI / CLEI:  
PBP3F05DAA**

## **Ordering Information:**

**TRR-LXP1500 Rectifier, LORAIN LXP1500 Power Supply Repair  
TAG Refurbishment TRR-LXP1500**

**BEFORE ORDERING, PLEASE CALL or EMAIL:  
856-753-8585 - [custsvcs@tagcords.com](mailto:custsvcs@tagcords.com)**

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)  
**Telecom Assistance Group**

Telephone: (856) 753-8585  
Fax: (856) 768-7645