

TAG Refurbishing - Lorain, LXC300 LX Controller

- Replace Necessary Components

Repair Benefits:

- Save Engineering \$\$ on new OSP equipment
- Ease of Replacement "Swap out"



**HECI / CLEI:
PBP3QSVDTA**

Ordering Information:

**TRR-LXPC-01 Rectifier, LORAIN LXC300 LX Controller Repair
TAG Refurbishment TRR-LXPC-01**

**BEFORE ORDERING, PLEASE CALL or EMAIL:
856-753-8585 - custsvcs@tagcords.com**

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585
Fax : (856) 768-7645