


80 Type / SLC 2000 Cabinet Solutions for CenturyLink

New Heat Exchanger, Fan & Alarm Control Replacements

Heat Exchangers

TAG # TF-SLC201-02
(NEW Heat Exchanger)
CenturyLink MAT # 1337731




(2) MOUNTED ON CABINET SIDE (TOP & BOTTOM)



TAG # TFC-LU4-01
(NEW Alarm Control Board)
CenturyLink MAT # 1355244

(1) ALARM BOARD PER TRAY

4A / 4B Fan Trays




TAG # TF-SLC201 (NEW 48V Fan)

CenturyLink MAT # 1336047


(2) FAN TRAYS SHOWN IN THIS CABINET (4 FANS TOTAL)

Fans are shown installed in existing fan tray, *the tray IS NOT included*


(NEW Power Cables for 4A/4B Fan Trays are available, order # TFCS-LU4APA-06)



116A Control Unit (Battery)
- reverse side of cabinet



116A Board
(1) PER CABINET



TAG # TFC-116A-01
(NEW Alarm Control Board for Lucent 116A Battery Unit)
CenturyLink MAT # 1459078

114A Control Unit




TAG # TFC-114A-01*
(NEW Heat Exchanger Control Unit)

CenturyLink MAT # 1355243

* if metal housing is not needed, order # TFC-LU4-01
CenturyLink MAT # 1355244

TAG # TF-SLCBC-01
(NEW Battery Cooling Fan)
(1) FAN PER CABINET
CenturyLink MAT # 1461343



Battery Cooling

80 TYPE CABINET (INSIDE VIEW)









150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax: (856) 768-7645

Ordering Information:			
<p>TF-SLC201-02 MAT # 1337731</p>	<p>48V Heat Exchanger for 80 Type Cabinet w/ Screw on Connector <i>(Equiv. to KS23912L4)</i> <i>(80 Type Cabinet - External)</i></p>		
<p>TF-SLC201 MAT # 1336047</p>	<p>48V Fan for SLC 2000 4A / 4B Fan Trays w/ 5 Wire Plug <i>(Equiv. to KS23912L6)</i> <i>(80 Type Cabinet, SLC 2000 Tray - Internal)</i> (Replacement Power Cables for Lucent 4A/4B Fan Trays are available, order # TFCS-LU4APA-06 - call for pricing)</p>		
<p>TFC-114A-01 MAT # 1355243</p>	<p>114A Fan Control Unit Replacement for 80 Type Cabinet Heat Exchangers <i>(Equiv. to 106894934)</i> (includes metal housing w/ alarm control board)</p>	<p># TFC-114A-01</p> 	<p># TFC-LU4-01</p> 
<p>TFC-LU4-01 MAT # 1355244</p>	<p>Alarm Control Board Replacement for Lucent 4A/4B, 4G/SLC 2000 Fan Trays & 114A Control Units (control board only - customer supplied fan trays / 114A housing)</p>		
<p>TF-SLCBC-01 MAT # 1461343</p>	<p>48V Cooling Fan for 80 Type Cabinet Battery Compartment w/ 3 Wire Plug</p>	<p># TF-SLCBC-01</p> 	<p># TFC-116A-01</p> 
<p>TFC-116A-01 MAT # 1459078</p>	<p>Alarm Control Board for Lucent 116A Battery Fan Unit (control board only - customer supplied metal housing)</p>		

150 Cooper Rd. (F-15)
 W. Berlin, NJ 08091

www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax : (856) 768-7645