

# Litespan 2000 (LSC-2020) Cabinet Solutions

# New Fan & Heat Exchanger Replacements

**TAG # TF-LS2000-44**

(NEW Replacement DFA Fan Kit -  
(4) New Fans per Kit)

**(3) TRAYS ARE  
SHOWN IN  
THIS CABINET  
(3 KITS = 12 FANS)**




Kit is shown installed  
in existing DFA fan tray,  
*the tray IS NOT included*


**TAG # TF-LS2000-03**

(NEW Replacement Heat Exchanger)

**(2) IN EACH  
HEAT STACK  
(TOP & BOTTOM)**



**LSC-2020 CABINET (OUTSIDE VIEW)**



**LSC-2020 CABINET (INSIDE - FRONT VIEW)**

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

**Telecom Assistance Group**

Telephone: (856) 753-8585

Fax : (856) 768-7645

## Litespan 2000 (LSC-2020) Cabinet Solutions

## New Fan &amp; Heat Exchanger Replacements

<p><b>Ordering Information:</b></p> <p><b>TF-LS2000-03</b></p>	<p>48 Volt Replacement Heat Exchanger for <b>Litespan 2000 Cabinet Heat Stack</b></p> <p>w/ 3 Unterminated Leads - Red (+48 Return), Black (-48V), Blue (Sensor)</p> <p><i>Includes (3) Butt Splices</i></p>	
<p><b>TF-LS2000-44</b></p>	<p><b>Litespan 2000 DFA Fan Kit</b></p> <p>(4) <u>NEW</u> 48V Replacement Fans w/ Guard Grills <i>- includes (16) plastic rivets &amp; (4) zip ties</i></p> <p>(1) <u>NEW</u> Wiring Harness w/ 12 Wire Plug <i>use in existing DFA DC Fan Assembly <u>500-1100-XXX</u></i></p> <p><i>Individual fans (for splicing) can also be ordered, for a qty of (1) fan, order PN # TF-LS2000-04</i></p>	 <p><i>(fans only - tray is not included)</i></p>

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

**Telecom Assistance Group**

Telephone: (856) 753-8585

Fax : (856) 768-7645