
Nortel DMS OPM Cabinet Solutions

Refurbished Tray Upgrade & New Fan Replacements



150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com Telecom Assistance Group



Copyright © 2020 by Telecom Assistance Group, Inc.

datasheets\Fans\OSP Cabinet\DMS\TAG_Nortel_DMS_OPM_Cabinet_Solutions_r01.dsf (11/17/20)

Nortel DMS OPM Cabinet Solutions

Refurbished Tray Upgrade & New Fan Replacements

Ordering Information:			
TFR-8X06ABT BEFORE ORDERING, PLEASE CALL or EMAIL: 856-753-8585 custsvcs@tagcords.com	 TAG Refurbishing - Paddleless Alarm Conversion Upgrade for NT8X06AB Fan Trays found in DMS OPM Cabinets Includes: (1) Recycled NT8X06AB Fan Tray upgraded w/ (4) DMS OPM Fans - 3 Wire, 48VDC (1) Fan Alarm Control Board (no paddles needed) (includes mounting bracket) 	REFURBISHED FAN TRAY w/ 2YR WARRANTY ALARM CONTROL BOARD (no paddles)	
TF-DMS06	48V Fan for Booster Fan Unit (BFU) found in DMS OPM Cabinets w/ Power Prongs, Unterminated Tach Lead & (1) Butt Splice (Equiv. to MD48B9X)		

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com Telecom Assistance Group



Copyright © 2020 by Telecom Assistance Group, Inc.

datasheets\Fans\OSP Cabinet\DMS\TAG_Nortel_DMS_OPM_Cabinet_Solutions_r01.dsf (11/17/20)