
#### **36B Cabinet Solutions for AT&T**

## **New Replacement Fan, Control Board & Accessories**



### TAG # T-6W3F-05

(NEW Protector / 526A to 125 Station Protector)

(1) IN EACH CABINET



(NEW 48V "2C" Fan w/ 3 Wire Plug)

AT&T PID # ATT.200002997

(1) FAN TRAY UNIT IN EACH CABINET (3 FANS)



**36B CABINET (OUTSIDE VIEW)** 



**INSIDE VIEW OF CABINET** 





TAG # TFC-LU2BC-01

(NEW Alarm Control Board for "2C" Fan Tray)

AT&T PID # ATT.200006513

(1) ALARM BOARD PER TRAY

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

**Telecom Assistance Group** 

Telephone: (856) 753-8585

Fax: (856) 768-7645

## **36B Cabinet Solutions for AT&T**

# **New Replacement Fan, Control Board & Accessories**

Ordering Information:		
TF-LU2C <u>AT&amp;T PID #</u> ATT.200002997	48V Fan for Lucent <u>2C</u> Fan Tray w/ 3 Wire Plug  (Equiv. to KS22501L5A)  (36B Cabinet, Lucent 2C Tray - Internal)	TF-LU2C ANUDC SJAA  TAGINC  TA
TFC-LU2BC-01  AT&T PID #  ATT.200006513	Alarm Control Board for Lucent 2B & <u>2C</u> Fan Trays (control board only - customer supplied fan trays)	
T-6W3F-05	Protector / 526A plug to 125 Station Protector (5') - available in various lengths  (36B Cabinet, Test Cord - Internal)  • Cabinet mounting assembly for performing line tests on SLC-96 & Series 5	125 Station Protector  (5')  463A  526A

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585 Fax: (856) 768-7645