
## Litespan 2000 (LSC-2020) Cabinet Solutions for AT&T

## New Heat Exchanger, Fan & Alarm Control Replacements



www.tagcords.com **Telecom Assistance Group** 

(856) 768-7645 datasheets\AT&T\TAG LSC-2020 Cabinet Solutions ATT r05.dsf (04/16/19)

(856) 753-8585

Telephone:

Fax:

W. Berlin, NJ 08091 Copyright © 2019 by Telecom Assistance Group, Inc.

150 Cooper Rd. (F-15)

## Litespan 2000 (LSC-2020) Cabinet Solutions for AT&T

## New Heat Exchanger, Fan & Alarm Control Replacements

Ordering Information	on:	
TF-LS2000-03 <u>AT&amp;T PID #</u> ATT.200004394	48V Heat Exchanger for Litespan 2000 Cabinet Heat Stack w/ 3 Unterminated Leads - Red (+48 Return), Black (-48V), Blue (Sensor) Includes (3) Butt Splices	TF-LS200-03 WF:DC: 30W 0.726 BB:WF:DC: 30W CTASING TASING
TF-LS2000-44 <u>AT&amp;T PID #</u> ATT.200004556	<ul> <li>Litespan 2000 DFA Fan Kit</li> <li>(4) <u>NEW</u> 48V Fans w/ Guard Grills - includes (16) plastic rivets &amp; (4) zip ties</li> <li>(1) <u>NEW</u> Wiring Harness w/ 12 Wire Plug use in existing DFA DC Fan Assembly <u>500-1100-XXX</u> Individual fans (for splicing) can also be ordered, for a qty of (1) fan, order PN # TF-LS2000-04, <u>AT&amp;T PID #</u> ATT.200004558</li> </ul>	<i>(fans only - tray is not included)</i>
TFC-DFA-01 <u>AT&amp;T PID #</u> ATT.200006507	Alarm Control Board for Litespan 2000 DFA Fan Trays <i>use in existing DFA DC Fan Assembly <u>500-1100-XXX</u></i>	The of A of Trace Rec.
150 Cooper Rd. (F-15) W. Berlin, NJ 08091	www.tagcords.com Telecom Assistance Group	Telephone: (856) 753-8585 • Fax : (856) 768-7645

Copyright © 2019 by Telecom Assistance Group, Inc.

datasheets\AT&T\TAG\_LSC-2020\_Cabinet\_Solutions\_ATT\_r05.dsf (04/16/19)