Purcell Cabinet Solutions for AT&T **New Heat Exchanger Replacements TAG # TF-MC133-01 TAG # TF-MC175-04** (175mm) (133mm) AT&T PID # ATT.200004388 AT&T PID # ATT.200004555 (NEW "Door" Heat Exchanger) (NEW Heat Exchanger*) **AT LEAST** M (1) IN EACH (3) IN EACH CABINET CABINET *(for Fan Kit with Bracket, order # TF-MC175-04-KIT. order AT&T PID # ATT.200004577) **PURCELL FLEXAIR 741 CABINET PURCELL A009 CABINET VIEW OF CABINET** WITH THE DOOR OPEN 15 AND FAN COVER PLATE MDSNCTDR REMOVED



www.tagcords.com Telecom Assistance Group



Copyright © 2023 by Telecom Assistance Group, Inc.

datasheets\AT&T\TAG_Purcell_Cabinet_Solutions_ATT_r03.dsf (03/21/23)

Purcell Cabinet Solutions for AT&T

New Heat Exchanger Replacements

Ordering Information: TF-MC133-01 <u>AT&T PID #</u> ATT.200004388	(133mm) Heat Exchanger for Purcell FlexAir 741 Cabinet Doors w/ 4 Leads & Faston Connectors (fan only - use with existing mounting bracket)	(133mm)
TF-MC175-04 <u>AT&T PID #</u> ATT.200004555	(175mm) Heat Exchanger for Purcell A009 Cabinets w/ Weatherproof Connector (fan only - use with existing mounting bracket) (for Fan Kit with Bracket, order # TF-MC175-04-KIT, order <u>AT&T PID #</u> ATT.200004577)	

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com
Telecom Assistance Group



Copyright ©2023 by Telecom Assistance Group, Inc.