
Litespan 2000 Cabinet Solutions for Lumen/CenturyLink

New HX, Fans & Alarm Control Replacements



150 Cooper Rd. (F-15) W. Berlin, NJ 08091

www.tagcords.com
Telecom Assistance Group



Copyright © 2024 by Telecom Assistance Group, Inc.

datasheets\CenturyLink\TAG_LS2000_Cabinet_Solutions_CLK_r02.dsf (02/05/24)

Litespan 2000 Cabinet Solutions for Lumen/CenturyLink

New HX, Fans & Alarm Control Replacements

Ordering Informati TF-LS2000-03 MAT # 1359389	48V Heat Exchanger for Litespan 2000 Cabinet Heat Stack w/ 3 Unterminated Leads - Red (+48 Return), Black (-48V), Blue (Sensor) Includes (3) Butt Splices	TF-LS200-03 WTD DS SW 0726 WTD DS SW 0726 W
TF-LS2000-44 MAT # 1445489	Litespan 2000 DFA Fan Kit(4) NEW 48V Fans w/ Guard Grills - includes (16) plastic rivets & (4) zip ties(1) NEW Wiring Harness w/ 12 Wire Plug use in existing DFA DC Fan Assembly 500-1100-XXX Individual fans (for splicing) can also be ordered, for a qty of (1) fan, order # TF-LS2000-04, MAT # 1445620	(fans only - tray is not included)
TFC-DFA-01 MAT # 1458948	Alarm Control Board for Litespan 2000 DFA Fan Trays <i>use in existing DFA DC Fan Assembly <u>500-1100-XXX</u></i>	
TF-LPM-01	48V Fan for Lorain Power Modules w/ Power Prongs (fan only - use in existing Lorain 427215900 Power Modules)	(fan only - module is not included) #TF-LPM-01 (INSTALL THE NEW TAG FAN INTO EXISTING POWER MODULE)
Cooper Rd. (F-15) Berlin, NJ 08091	www.tagcords.com Telecom Assistance	Telephone: (856) 753-85 Group Fax : (856) 768-76

Copyright © 2024 by Telecom Assistance Group, Inc.

datasheets\CenturyLink\TAG_LS2000_Cabinet_Solutions_CLK_r02.dsf (02/05/24)