
## Mesa 2 Cabinet Solutions for Lumen/CenturyLink

## **New Heat Exchanger & ECU Replacements**



150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585 Fax: (856) 768-7645

## **Mesa 2 Cabinet Solutions for Lumen/CenturyLink**

## **New Heat Exchanger & ECU Replacements**

Ordering Information:		
TF-MC225-01 <u>Lumen/CLK MAT #</u> 1345222	(225mm) Heat Exchanger for Mesa Cabinet (Top) w/ Round Weatherproof Connector  (fan only - use with existing mounting bracket)	
TF-MC225-02-KIT <u>Lumen/CLK MAT #</u> 1451725	(225mm) Heat Exchanger KIT for Mesa Cabinet (Bottom) w/ 4 Wire Plug & Mounting Bracket for Fan without the Bracket, order # TF-MC225-02, MAT # 1345223  for the Mounting Bracket only, order TFB-MC225-02, MAT # 1451078)	1-12-12-12
TFC-MESA-04	4 Port Environmental Control Unit (ECU) Replacement for Mesa 2 Cabinets used in the DSLAM 192 & DSLAM 384 Type Cabinets	10   10   10   10   10   10   10   10

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585 Fax: (856) 768-7645

datasheets\CenturyLink\TAG\_Mesa2\_Cabinet\_Solutions\_CLK\_r06.dsf (02/12/24)