


Nortel DMS OPM Cabinet Solutions for Frontier

Refurbished Tray Upgrade & New Fan Replacements




UPN # TF-DMS06
(NEW Replacement Fan)
(3) FANS PER BFU



BOOSTER FAN UNIT (BFU)

**TAG will UPGRADE your fan tray
ELIMINATING THE NEED FOR PADDLES!**



NT8X06AB
(2 TRAYS PER CABINET)

TAG # TFR-8X06ABT

(TAG Refurbished **UPGRADE**)
(see following page for picture)



NORTEL DMS OPM CABINET (OUTSIDE VIEW)



NORTEL DMS OPM CABINET (INSIDE VIEW)

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com
Telecom Assistance Group

Telephone: (856) 753-8585
Fax : (856) 768-7645

Ordering Information:


TFR-8X06ABT

**BEFORE ORDERING,
PLEASE CALL or EMAIL:**

**856-753-8585
custsvcs@tagcords.com**

**TAG Refurbishing -
Paddleless Alarm Conversion Upgrade
for NT8X06AB Fan Trays
found in DMS OPM Cabinets**

Includes:
(1) Recycled NT8X06AB Fan Tray upgraded
w/ (4) DMS OPM Fans - 3 Wire, 48VDC
&
(1) Fan Alarm Control Board (no paddles needed)
(includes mounting bracket)



**FTR UPN #
TF-DMS06**

**48V Fan for Booster Fan Unit (BFU)
found in DMS OPM Cabinets**

*w/ Power Prongs, Unterminated Tach Lead
& (1) Butt Splice*

