Nortel OPAC / OPM Cabinet Solutions

New Fan Replacements

INNER CEILING VIEW



TAG # TF-NTOPAC

(NEW Replacement Fan)




TAG # TF-NTOPAC-02

(NEW Replacement Fan)




Average of (12 or 16) Fans in Each Cabinet *

* Order Fans by <u>CONNECTOR</u> <u>TYPE</u> (see the following page for connector detail)





NORTEL OPAC / OPM CABINET (OUTSIDE VIEW)



NORTEL OPAC / OPM CABINET (INSIDE VIEW)



TRAY VIEW FANS w/ WEATHERPROOF PLUG
(2) FANS PER TRAY



TRAY VIEW -FANS w/ SEALED 3 PIN PLUG (2) FANS PER TRAY

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group


Telephone: (856) 753-8585 Fax: (856) 768-7645

Nortel OPAC / OPM Cabinet Solutions

New Fan Replacements

Ordering Information: TF-NTOPAC	48 Volt Replacement Fan for Nortel Opac / OPM Cabinet w/ Round Weatherproof Connector (fan only - use with existing guard grill)	TF-NTOPAC 48/Y=TPC B BAN, BLACK VV RED V, CTAG INC. THE RE WAY BEEN BEEN BEEN BEEN BEEN BEEN BEEN BEE
TF-NTOPAC-02	48 Volt Replacement Fan for Nortel OPAC / OPM Cabinet w/ Sealed 3 Pin Plug (fan only - use with existing guard grill)	TF-NTOPAC-92 48V="DC 0.40A TAG INC. Tentration" FM CC

- Fans are also available with an alternate type of Sealed 3 Pin Connector, order # TF-NTOPAC-04 (used w/ NT7A6986 adapter)
- Fans are available without a Connector (for splicing), order # TF-NTOPAC-3
- Guard Grill Replacement Kits are available, order # TFG-162KIT-01



150 Cooper Rd. (F-15) W. Berlin, NJ 08091

www.tagcords.com **Telecom Assistance Group** Telephone: (856) 753-8585

(856) 768-7645

Fax: