
36B Cabinet Solutions for Verizon

New Replacement Fan, Control Board & Accessories



TAG # T-6W3F-10

(NEW Protector / 526A to 125 Station Protector)

VZ ID # 1100 7887

(1) IN EACH CABINET

TAG # TF-LU2C


(NEW 48V "2C" Fan w/ 3 Wire Plug)

VZ ID # 1132 7078

(1) FAN TRAY UNIT IN EACH CABINET (3 FANS)



36B CABINET (OUTSIDE VIEW)



INSIDE VIEW OF CABINET





TAG # TFC-LU2BC-01

(NEW Alarm Control Board for "2C" Fan Tray)

(1) ALARM BOARD PER TRAY

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone:

(856) 753-8585

Fax: (856) 768-7645

Ordering Information: TF-LU2C VZ ID # 1132 7078	48V Fan for Lucent <u>2C</u> Fan Tray w/ 3 Wire Plug (Equiv. to KS22501L5A) (36B Cabinet, Lucent 2C Tray - Internal)	TF-LUZC AVCTION S.MA TAG INC. Factorises PA (1)
TFC-LU2BC-01	Alarm Control Board for Lucent 2B & <u>2C</u> Fan Trays (control board only - customer supplied fan trays)	Tecument of the second of the
T-6W3F-10 VZ ID # 1100 7887	Protector / 526A plug to 125 Station Protector (10') - available in various lengths (36B Cabinet, Test Cord - Internal) • Cabinet mounting assembly for performing line tests on SLC-96 & Series 5	125 Station Protector (10') 463A 526A

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585 Fax: (856) 768-7645