

Alcatel 1631* Replacement Fans



"Alcatel 1631"

PN # TF-ALC1631-02
48V Replacement Fan for
Alcatel 1631 Blower Assembly
w/ Power Prongs,
Unterminated Tach Lead &
(1) Butt Splice

(fan only - use with existing guard grill)

*(use in Blower Assembly
3AL45446AA)*



BLOWER ASSEMBLY # 3AL45446AA w/ 3 EXISTING FANS
(Blower Assembly is not included)

Ordering Information:

TF-ALC1631-02 **48 Volt Replacement Fan for
Alcatel 1631 Blower Assembly
w/ Power Prongs, Unterminated Tach Lead
& (1) Butt Splice**
(fan only - use with existing guard grill)
(use in # 3AL45446AA blower assembly)

VZ ID

7501 3926

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group