



Carrier VoIP Replacement Fans



VZ ID #
7501 3417
1086 3884 (VZB)




"Nortel IW SPM-IP"

PN # TF-DMS-FOS
48 Volt Replacement Fan for
Nortel IW SPM-IP
NTLX56AA fan assemblies*

used in **Nortel IW SPM-IP NTLX55AA** cooling units

* fan only, arm assembly is not included




FRONT VIEW OF →
NTLX56AA FAN ASSEMBLY
(NOT SUPPLIED)

"Media Gateway 9000"

PN # TF-MG9K-01
Nortel / GENBAND Media Gateway 9000
48 Volt Replacement Fan

w/ 3 Wire Plug
(for use in **NTNY18AA** Cooling Unit)



VZ ID #
1135 1548
1096 1989 (VZB)

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group