


Carrier VoIP Replacement Fans




"Nortel IW SPM-IP"


PN # TF-DMS-FOS
48 Volt Replacement Fan for
Nortel IW SPM-IP
NTLX56AA fan assemblies*

(used in **Nortel IW SPM-IP NTLX55AA** cooling units)

* fan only, arm assembly is not included



← PN # TF-DMS-FOS



FRONT VIEW OF
NTLX56AA FAN ASSEMBLY
(NOT SUPPLIED)

Ordering Information:

TF-DMS-FOS **48V Replacement Fan for Nortel IW SPM-IP**
NTLX56AA Fan Assemblies
(used in **Nortel IW SPM-IP NTLX55AA** cooling units)
(fan only, arm assembly is not included)

VZ ID #
7501 3417
1086 3884 (VZB)

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group