

# OSP Cabinet Replacement Fans & Alarm Control Boards

## "LS2000 Heat Exchangers"



**VZ ID #**  
**1132 9780**

**PN # TF-LS2000-03**  
48V Heat Exchanger for  
Litespan 2000 Cabinet Heat Stack

w/ 3 Unterminated Leads -  
Red (+48 Return), Black (-48V), Blue (Sensor)  
*Includes (3) Butt Splices*



**PN # TF-LS2KSB-01**  
48V Heat Exchanger for  
Litespan 2000  
Cabinet Heat Stack

w/ Power Prongs

**VZ ID #**  
**7501 0344**

## LS2000 CABINET (OUTSIDE VIEW)




## "DFA Fans & Alarm Control Boards"

**PN # TF-LS2000-44**  
Litespan 2000 DFA Fan Kit

**VZ ID #**  
**1136 1758**


### Kit includes:

- (4) NEW 48V Fans w/ Guard Grills  
- includes (16) plastic rivets & (4) zip ties
- (1) NEW Wiring Harness w/ 12 Wire Plug



**KIT SHOWN INSTALLED IN EXISTING DFA FAN TRAY \***  
*\*(DFA FAN TRAY IS NOT INCLUDED)*

**NEW** Alarm Control Boards  
are also available, order  
# **TFC-DFA-01** (VZ ID # 7501 3160)



use in existing DFA,  
DC Fan Assembly **500-1100-XXX**

*Individual fans (for splicing) can also be ordered,  
for a qty of (1) fan, order # **TF-LS2000-04**  
(VZ ID # 1136 1757)*

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585  
Fax : (856) 768-7645

**Telecom Assistance Group**