OSP Cabinet Replacement Fans & Alarm Control Boards



"Lucent 2B"


PN # TF-LU2B

48 Volt Replacement Fan for Lucent <u>2B</u> Fan Tray

w/ 3 Wire Plug

(Equiv. to KS22501L5A)

INSIDE VIEW OF 80A/D CABINET



NEW Alarm Control Boards are also available, order # TFC-LU2BC-01 (VZ ID # 1137 8148)





LUCENT 2B FAN TRAY
w/ (3) EXISTING FANS (BOTTOM VIEW)
 (fan tray is not included)

Ordering Information:		VZ ID#
TF-LU2B	48V Fan for Lucent <u>2B</u> Fan Tray w/ 3 Wire Plug (Equiv. to KS22501L5A)	1132 3437
TF-SLC5-01	48V Fan for SLC5 Cabinet <u>2B</u> Fan Tray w/ 3 Wire Plug (Equiv. to KS22501L5A) - (not shown)	1132 1557
TFC-LU2BC-01	Alarm Control Board for Lucent 2B & 2C Fan Trays (customer supplied fan trays)	1137 8148
TFCS-2BPWRY-01	Power Cable "Y" for Lucent <u>2B</u> & 2C Fan Trays w/ 1 Male Connector to Female "Y", (1') - (not shown)	
TFCS-2BRS-08	Remote Sensing Daisy Chain Cable for Lucent 2B & 2C Fan Trays w/ 2 Wires & Connectors, (8') - (not shown)	

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 Telephone: (856) 753-8585

www.tagcords.com Fax: (856) 768-7645

Telecom Assistance Group