Alcatel 1680* Replacement Fans



"Alcatel 1680"

PN # TF-ALC1680-01

48 Volt Replacement Fan for Alcatel 1680 OGX Blower Assembly

> w/ Power Prongs, Unterminated Tach Lead & (1) Butt Splice

(fan only - use with existing guard grill)

(use in # 3EM04820AA, HECI WMMYAA9FAA)

BLOWER ASSEMBLY # 3EM04820AA w/ 3 EXISTING FANS

(blower assembly is not included)



Ordering Information:

TF-ALC1680-01 48 Volt Replacement Fan for

Call for Pricing

Alcatel 1680 OGX Blower Assembly

w/ Power Prongs, Unterminated Tach Lead & (1) Butt Splice

(fan only - use with existing guard grill)

(use in # 3EM04820AA blower assembly, HECI WMMYAA9FAA)

150 Cooper Rd. (F-15) W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585

Fax: (856) 768-7645

Telecom Assistance Group