

# Lucent DACS III / IV\* Replacement Fans




**PN # TF-DACS3/4-01**  
**Lucent DACS III / IV**  
48 Volt Replacement Fan  
w/ 4 Wire Plug


**Equiv. to KS23913L1,**

**Used in Lucent Fan Assemblies:**  
DACS III (ED-2C816-30, G1 or ED-2C906-30)  
DACS IV (WP92310L4)

**DACS IV FAN ASSEMBLY**  
**(WP92310, L4)**  
*(fan assembly is not included)*



**4 WIRE  
PLUG**



*(front / top view)*



*(back / bottom view)*

## **Application:**

TAG's PN # TF-DACS3/4-01 replaces defective 4 Wire 48 Volt fans in Lucent DACS III & DACS IV fan assemblies.

## **Ordering Information:**

<b>TF-DACS3/4-01</b>	<b>Lucent DACS III / IV 48 Volt Replacement Fan</b>	<b>Call for Pricing</b>
	<b>w/ 4 Wire Plug</b> ( <i>Equiv. to KS23913L1</i> ),	
	<i>Used in Lucent Fan Assemblies: DACS III (ED-2C816-30, G1 or ED-2C906-30)</i>	
	<i>DACS IV (WP92310L4)</i>	

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585  
Fax : (856) 768-7645

**Telecom Assistance Group**