


# OSP Cabinet Replacement Fans & Alarm Control Boards



## "Litespan PDFA"


**PN # TF-LS2000-01**

48 Volt Replacement Fan for  
**Litespan 2000 Power Distribution (PDFA)**


Square Fan w/ 3 Wire Plug & Guard Grill  
(includes plastic rivets)

(use in PDFA Fan Tray # 500-1126-723)

**NEW** Alarm Control Boards  
are also available,  
order # **TFC-PDFA-X2**



(2 ALARM CONTROL BOARDS  
ARE USED IN EACH TRAY)



**FAN TRAY # 500-1126-723**  
**w/ (4) EXISTING FANS**  
(fan tray is not included)

## Ordering Information:

**TF-LS2000-01**

**48 Volt Replacement Fan for LS2000 PDFA,**  
**Square Fan w/ 3 Wire Plug & Guard Grill**  
(includes plastic rivets) (use in PDFA Fan Tray # 500-1126-723)

**Call for Pricing**

**TFC-PDFA-X2**

**Alarm Control Board for LS2000 PDFA Fan Trays**  
(equiv. to # 300-8205-900) (use in PDFA Fan Tray # 500-1126-723)

150 Cooper Rd. (F-15)  
W. Berlin, NJ 08091

[www.tagcords.com](http://www.tagcords.com)

Telephone: (856) 753-8585  
Fax : (856) 768-7645

**Telecom Assistance Group**