

OSP Cabinet Heat Exchangers & ECU

"Cell Site Mesa Bridge Cabinet"

PN # TF-MC179-01A
Heat Exchanger Replacement for
Mesa Bridge Cabinet (Upper - Internal)
w/ 4 Wire Female Weatherproof Plug


**Need a NEW Alarm Controller
ECU for this Cabinet ?
Order PN # TFC-MESA-01**




MESA BRIDGE CABINET
(FRONT VIEW)



MESA BRIDGE CABINET
(RIGHT SIDE - FAN VIEW)



TF-MC179-01A



Ordering Information:

TF-MC179-01A	Heat Exchanger for Cell Site Mesa Bridge Cabinet (Upper - Internal) w/ 4 Wire Female Weatherproof Plug	Call for Pricing
TF-MC179-01	Heat Exchanger for Cell Site Mesa Bridge Cabinet (Lower - Door) w/ 4 Wire Female Weatherproof Plug - (not shown)	
TFC-MESA-01	2 Port Mesa Cabinet Environmental Control Unit (ECU) - (not shown) (used in Mesa Cell Site Cabinets: XL, SOLE, Span XL, Bridge, Edge & Sport)	

150 Cooper Rd. (F-15)
W. Berlin, NJ 08091

www.tagcords.com

Telephone: (856) 753-8585
Fax : (856) 768-7645

Telecom Assistance Group