




7330 Testing Diagrams (OSP)

Option 1 - TESTING THRU CABLES




Cabinet



TEST 2

TEST 1

X-Box





25' to 100'

TEST 1

TEST 2

7330 Testing Diagrams (OSP)

Option 2 - TESTING THRU CIRCUIT PACK



Telecom Assistance Group (TAG)
856-753-8585 www.tagcords.com

F1 - Feeder Cable (from CO)
F2 - Toward Customer