Litespan 2000 (LSC-2030) Cabinet Solutions

New HX, Fans & Alarm Control Replacements

TAG # TF-ACABTZ-01A

CAMPATA CONTROL OF THE CONTROL OF TH

MAT # 1359388

(NEW "Tarzan" Heat Exchanger) (2) IN EACH


(2) IN EACH
HEAT STACK
(TOP & BOTTOM)

TAG # TF-LS2000-44

MAT # 1445489

(NEW DFA Fan Kit - (4) New Fans per Kit)

(2) TRAYS ARE SHOWN IN THIS CABINET (2 KITS = 8 FANS)



Kit is shown installed in existing DFA fan tray, the tray IS NOT included




TAG # TFC-DFA-01


MAT # 1458948

(NEW DFA Alarm Control Board)

(1) ALARM BOARD PER TRAY



LSC-2030 CABINET HEAT STACK (OTHER SIDE OF CABINET)



LSC-2030 CABINET (INSIDE VIEW)



LSC-2030 CABINET (OUTSIDE VIEW)

150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (8

(856) 753-8585

Fax: (856) 768-7645

Ordering Information:

TF-ACABTZ-01A

MAT # 1359388

48V Heat Exchanger (Tarzan) for Litespan 2000 LSC-2030 Cabinet Heat Stack

w/ 3 Leads -

- (1) Amp Connector (Power, red / black wires) &
- (1) Amp Connector (Alarm, blue wire)

Includes: (1) Adapter Cable (# TFCS-ACABTZX) & (3) Butt Splices



TF-LS2000-44

MAT # 1445489

Litespan 2000 DFA Fan Kit

- (4) NEW 48V Fans w/ Guard Grills includes (16) plastic rivets & (4) zip ties
- (1) <u>NEW</u> Wiring Harness w/ 12 Wire Plug use in existing DFA DC Fan Assembly 500-1100-XXX

Individual fans (for splicing) can also be ordered, for a gty of (1) fan, order # TF-LS2000-04, MAT # 1445620



(fans only - tray is not included)

TFC-DFA-01

MAT # 1458948

Alarm Control Board for Litespan 2000 DFA Fan Trays

use in existing DFA DC Fan Assembly 500-1100-XXX



150 Cooper Rd. (F-15) W. Berlin, NJ 08091 www.tagcords.com

Telecom Assistance Group

Telephone: (856) 753-8585

Fax: (856) 768-7645